


# WARNING - IMPORTANT SAFETY NOTICE

Sept 2008

## PRODUCT RECALL

Tower Fan with Timer / Tower Fan with Remote Control



Micromark has identified a possible fault with the above fans that, with extensive continuous use, could cause the product to overheat and pose a potential fire risk.

### Model numbers affected: MM30142 and MM53597

**Only these 2 fan models are affected and the recall only applies to specific batches.**

Model and batch numbers are clearly indicated on a label on the rear of the product and on the base of the product retail box.

The recall only applies to batch numbers ending:

**0604, 0611, 0701, 0702, 0703 or 0704** (as circled above)

If you, or someone you know, owns one of the affected products please:

- 1) Stop using the fan immediately**
- 2) Return the product to the place of purchase where you will be given a replacement product or full refund.

For further information you can contact Micromark on

**FREEPHONE 0800 158 4401**

between 8.30am and 5pm Monday to Friday.

Please have your model number and batch number to hand when you call.

Alternatively see [www.micromark.co.uk/productrecall](http://www.micromark.co.uk/productrecall) for more information.

Micromark apologises for the inconvenience caused and thanks you for your co-operation.

**NO OTHER MICROMARK PRODUCT IS AFFECTED BY THIS RECALL**

**micromark**

550 White Hart Lane, London, N17 7RQ